



Kit, Carburetor Repair

RK2575702S



Replaces

Kohler

25 757 02, 25 757 02-S

Specifications

Manufacturer

Kohler

TURF Handels GmbH

Am Hartboden 48 Gratkorn, 8101

+43 3124 29064-17

<https://turf.rrproducts.com/>