


Replaces John Deere 1420 Rotary Mower Parts



60 & 72in Rear Discharge Deck - Model 2849 62in Deck Parts





Replaces John Deere 1420 Rotary Mower Parts



60 & 72in Rear Discharge Deck - Model 2849 62in Deck Parts

	R&R Part No.	OEM Part No.	Description	Qty Order Req Quantity
Rotai	ry Blades			
1	RM144935	M144935, TCU51118	Mower Blade - Mulcher - 22 x 3 x 1/4 in	3
Belts				
20	RTCU14356	TCU14356	V-Belt - Fits 62 in Decks	1
	Tech Note: Fit	ts 62 in Deck:		
Othe	r Parts Availa	ble		
44	RM141764	M141764	Eyebolt - Includes Flanged Locknut	1
45	RM163054	M163054	Grass Deflector - Upper	3
75	RM127353	M127353	Bushing	3
76	RM123569	M123569	Flange Nut	3
76	RM163055	M163055	Nut	3
77	R253-133	M85699	Seal - Oil	3
78	RM88251	M169375, M88251	Bearing - Spindle	6
79	RM127198	M127198	Seal	3
80	R19M7489	19M7489	Bolt Hex HD - M16 x 45 Gr 10.9	3
81	RM115245	M115245	Roller	4
82	RM123522	M123522	Washer - Belleville - Blade Bolt	3
83	RTCU38142	TCU14182, TCU38142	Hub - Sub For TCU51119 or TCU14182	3
84	RM123520	M123520	Washer - Hardened	3
85	R19M7868	19M7868	Bolt - M8-1.25 x 30 HHF	30

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces John Deere 1420 Rotary Mower Parts



60 & 72in Rear Discharge Deck - Model 2849 62in Deck Parts

	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
87	RTCA17524	TCA17524	Idler Pulley - 5 in Flat Dia with .75 in Brg ID	2	
90	RM163059	M163059	Spindle - 25 mm w/M16-2.0 Blade Bolt Thrd	3	
90	RM134382	M134382	Spindle - 25 mm w/M12-1.75 Blade Bolt Thrd	3	
91	RM141695	M112398, M141695	Idler - North America (Replaces M112398)	1	
92	R24M7226	24M7226	Washer - 13 x 35 x 5 mm	1	
93	RTCU51223	TCU51223	Deflector - Grass	3	
94	RM124203	M124203	Shaft	1	
95	RM136044	M136044	Spring - Extension	1	
96	RM133598	M133598	Shield	2	
97	R14M7400	14M7400	Locknut - 10mm	3	
101	RM163058	M127517, M163058	Bushing - Sub For M127517	3	
103	R93-2559	TCU23201	Bearing	2	
104	RM132309	M132309	Spacer	2	
105	RM163060	M133398, M163060	Washer - Replaces RM133398	3	