



# 1/2 Viton TU2K Ball Check Valve Repair Kit

RGCK2VRK005



## Details

Repair kits for True Union 2000 Single Entryl Ball Check Valves.

## Specifications

Manufacturer	Spars
Fitting Size	1/2
Seal Type	Viton

**TURF Handels GmbH**

Am Hartboden 48 Gratkorn, 8101  
+43 3124 29064-17

<https://turf.rrproducts.com/>