



6 Viton TU2K Ind Ball Check Valve Repair Kit RGCK2VRK060



Details

Repair kits for True Union 2000 Single Entryl Ball Check Valves.

Specifications

Manufacturer	Spars
Seal Type	Viton

TURF Handels GmbH

Am Hartboden 48 Gratkorn, 8101
+43 3124 29064-17

<https://turf.rrproducts.com/>