




NGK Spark Plug - R7376-10

RN4457



Replaces

Autolite	AR5383
Denso	IW01-31, IW06-31

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

TURF Handels GmbH

Am Hartboden 48 Gratkorn, 8101
+43 3124 29064-17

<https://turf.rrproducts.com/>