




Replaces Toro Greensmaster TriFlex

3320 Parts

Dethatching Unit - Model 04720

Groomer



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Greensmaster TriFlex

3320 Parts

Dethatching Unit - Model 04720
Groomer



Item No	R&R Part No.	OEM Part No.	Description	Qty Req	Order Quantity
---------	--------------	--------------	-------------	---------	----------------

Blades

1	R132-4626	132-4626	Groomer Blade - Helix .035 Thick	0	
---	------------------	----------	----------------------------------	---	--

Other Parts Available

10	R125-3478	125-3478	Groomer Shaft Assy	1	
11	R115-6869	115-6869	Bearing - Ball -Stainless	0	
12	R115-6923	115-6923	Shield - Bearing - Flocked	2	

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.